

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

**Fig. 1**

SW626  
SK-OV-3  
PA-1  
EB2  
OVCAR-3  
CABD-4  
CAOV-3

3DZ

Replacement Sheet

RECEIVED  
TECH CENTER 1600/2900  
OCT 23 2003



Replacement Sheet





Fig. 2



Replacement Sheet






Fig. 3





## Replacement Sheet

**FIGURE 4**



Replacement Sheet





Fig. 5



Replacement Sheet






FIGURE 6





## Replacement Sheet

**FIGURE 7**







Fig. 8

Replacement Sheet





## Replacement Sheet




**FIGURE 9**



## Replacement Sheet


**FIGURE 10**





## Replacement Sheet


FIGURE 11





## Replacement Sheet

FIGURE 12



a p<0.05 compared to negative controls

b not significant compared to negative control